


WIRING DIAGRAM



Please note:

1. Cold temperatures require up to 40 amp (below 0 Fahrenheit / -17 Celsius).
2. This wiring diagram is specific to the most common breakaway kits. However, there may be different breakaway kits, which use other wiring configurations and color codes. Therefore, you will need to check the specific manufacturers' specifications.